


A1058 Coast Road Improvement Scheme

For further information, email: roads@northtyneside.gov.uk, or Tel: (0191) 643 6500

Billy Mill Roundabout



Key Improvements

- Change the junction from a roundabout to signalised crossroads, which will increase its capacity and reduce peak delays.
- 2. Provide two lanes eastbound along Beach Road, from Billy Mill Roundabout to the A192 Tynemouth Pool roundabout.
- 3. Allow two lanes to travel ahead eastbound on the A1058 Coast Road approach to Billy Mill Roundabout.
- 4. Introduce a no right turn restriction from Beach Road onto Lynn Road to enable the smooth movement of traffic and remove the risk of collisions.
- 5. Introduce a new staggered signalised crossing at the petrol station on Beach Road to make it easier for people to cross the road.
- 6. Install a Toucan crossing on the Lynn Road arm of the junction to improve the continuity of the Coast Road Cycle Route.
- 7. Create an improved shared footway/cycleway from Billy Mill Roundabout to the A192 Tynemouth Pool Roundabout.
- 8. Introduce Keep Clear markings near the bus stop on the eastbound A1058 Coast Road at Billy Mill Roundabout to make it easier for buses to enter/exit the stops.
- 9. Widen the Regent Terrace approach to Billy Mill Roundabout to remove the conflict between filter lane traffic and vehicles waiting to go straight ahead, and add a Puffin crossing.

Key Improvements

- 1. Provide two northbound and two southbound lanes.
- Install traffic signals at both sliproad junctions, to make it easier for vehicles, particularly buses, to access Norham Road. Link these signals to those by Tesco for improved co-ordination of traffic movements.
- 3. Increase waiting capacity for vehicles on Norham Road that are turning right onto the sliproads.
- 4. Introduce new signalised crossing facilities on A1058 Coast Road entry and exit sliproads.
- 5. Introduce a Toucan crossing across Norham Road North to enhance the Coast Road Cycle Route.
- 6. Widen the sliproads to provide sufficient space for two vehicles side-by-side.

Norham Road Junction

